



- ➤ 1. It is suggested to use a flat desktop and place the parts in an orderly manner for quick assembly.
- > 2. Each step has assembly diagram and tips. Please read the installation techniques and precautions before assembly.
- > 3. The real color and size of some parts may be different from that in the manual, but the assembly method is the same.
- ➤ 4. Firmware has been uploaded to the motherboard in factory. After completing the assembly, please level the platform and load the filament then you could start the first test print.


#### **BACK**

#### **FRONT**






# Machine unboxing - top



Dongguan Kedong Electronic Technology Co., Ltd.

www.mixwarebot.com

# Machine unboxing - bottom






# Step 1 Frame assembly

- ① The installation of the frame is divided into two parts;
- ② Insert the aluminum profile into the slots of the corner code separately;
- M5X10 screws, use a 4mm allen wrench to lock the corner code and aluminum profile;











# Step 2 Platform assembly


vertically into the plastic parts for locking.


Kedong Electronic Technology Co., Ltd. www.mixwarebot.com














# Step 4 Extruder motor/Filament holder

Kedong Electronic Technology Co., Ltd. www.mixwarebot.com

① Use M4X8 screws and T-nuts to install the Extruder motor and Filament holder on the Y-axis aluminum profile;


② The installation height is about 30cm and 15cm away from the bottom surface. Lock the screws.







# Step 5 Screen/switch assembly






Green: Endstop wire

### Step 6 Mainboard wiring

Kedong Electronic Technology Co., Ltd. www.mixwarebot.com

5




both sides.



# Step 7 Adapter board assembly


- ① M4X8 screws pass through the holes of the shell;
- 2 Screw the t-nut into a part of the screw so that the direction of the nut is flat;
- 3 Put into the groove of the aluminum profile, the installation height is about 15cm away from the extruder motor,lock the screw;






# Step 8 Feed pipe assembly

Kedong Electronic Technology Co., Ltd. www.mixwarebot.com









# Step 10 Bottom cover assembly

Kedong Electronic Technology Co., Ltd. www.mixwarebot.com

