



## RS232 self-test



1.



Before running the Tech 2 self test:

1. CANdi must not be connected.
2. ALDL loopback should be connected (GM3000109).
3. Failure to follow these instructions may invalidate the self test.

Press [EXIT] to continue

4.

Tech 2 Self Test  
Version 6.40

- F0: Automated Main PCB and VCI
- F1: Automated Main PCB
- F2: Automated VCI
- F3: Selectable Main PCB**
- F4: Selectable VCI
- F5: Power On Self Test Results
- F6: Hardware ID

5.

## Main PCB Self Test

F0: RAM / ROM  
F1: RS-485 LoopBack  
F2: RS-232 LoopBack  
F3: Keypad  
F4: PCMCIA  
F5: Display Controller  
F6: Sound Transducer  
F7: Real-Time Clock

6.

## RS-232 Self Test

RS-232 Test: Passed

7.