


M7 Tool upgrade operation steps

AGM

M7 Driver and upgrade tool download

<https://mega.nz/file/LxNWRbjY#PWvRmYU-YIvMyKY8v0BJSKVOFqUVcl8kbr1fLgYmfJo>

Please unzip these 3 archives and put them in the same file directory




Here is an example of upgrading the EU software version, and the steps for the US software version.


Step1:First,installthedriverfiles,
If the computer has installed AGM M7 driver,you can skip to Step
4 directly。



Step 2: choose yes as following picture



Step3:You need to wait for about 15 minutes to delete the driver installation process,please be patient,After the installation is successful,please restart the computer




step 4: Open the upgrade tool

SP_Flash_Tool_Selector_exe_Windows_v1.2116.00.000


名称	修改日期	类型	大小
plugins	2021/4/20 15:55	文件夹	
SP_Flash_Tool_V5	2021/7/10 14:08	文件夹	
SP_Flash_Tool_V6	2021/4/20 15:55	文件夹	
FlashToolSelector.exe	2021/4/22 10:06	应用程序	279 KB
Qt5Core.dll	2021/4/20 15:39	应用程序扩展	6,049 KB
Qt5Gui.dll	2021/4/20 15:39	应用程序扩展	6,963 KB
Qt5Widgets.dll	2021/4/20 15:39	应用程序扩展	5,466 KB
Qt5Xml.dll	2021/4/20 15:39	应用程序扩展	191 KB

codecs	2021/4/20 15:55	文件夹	
imageformats	2021/4/20 15:55	文件夹	
sqldrivers	2021/4/20 15:55	文件夹	
assistant.exe	2021/4/19 16:49	应用程序	1,181 KB
BromAdapterTool.ini	2021/4/19 16:49	配置设置	1 KB
console_mode.xsd	2021/4/19 16:49	XSD 文件	29 KB
CustPT.ini	2021/4/19 16:49	配置设置	1 KB
DA_PL.bin	2021/4/19 16:49	BIN 文件	17,297 KB
DA_PL_CRYPT020.bin	2021/4/19 16:49	BIN 文件	17,297 KB
DA_SWSEC.bin	2021/4/19 16:49	BIN 文件	2,144 KB
DA_SWSEC_CRYPT020.bin	2021/4/19 16:49	BIN 文件	2,144 KB
dl_without_scatter.xml	2021/4/19 16:49	XML 文档	2 KB
download_scene.ini	2021/4/19 16:49	配置设置	1 KB
flash_tool.exe	2021/4/19 16:49	应用程序	10,352 KB
flashtool.qch	2021/4/19 16:49	QCH 文件	8,172 KB
flashtool.qhc	2021/4/19 16:49	QHC 文件	12 KB
FlashToolLib.dll	2021/4/19 16:49	应用程序扩展	1,459 KB
FlashToolLib.v1.dll	2021/4/19 16:49	应用程序扩展	2,909 KB
FlashtoollibEx.dll	2021/4/19 16:49	应用程序扩展	4,925 KB
history.ini	2021/7/10 14:10	配置设置	1 KB
key.ini	2021/4/19 16:49	配置设置	3 KB
msvc90.dll	2021/4/19 16:49	应用程序扩展	556 KB
msvcr90.dll	2021/4/19 16:49	应用程序扩展	641 KB
MTK_AllInOne_DA.bin	2021/4/19 16:49	BIN 文件	17,361 KB
option.ini	2021/7/10 14:10	配置设置	1 KB
phonon4.dll	2021/4/19 16:49	应用程序扩展	261 KB
platform.xml	2021/4/19 16:49	XML 文档	32 KB
QtCLucene4.dll	2021/4/19 16:49	应用程序扩展	873 KB
QtCore4.dll	2021/4/19 16:49	应用程序扩展	2,239 KB
QtGui4.dll	2021/4/19 16:49	应用程序扩展	8,031 KB
QtHelp4.dll	2021/4/19 16:49	应用程序扩展	419 KB


step5:load software package




step6:When you finish loading the software,click the download button



step 7: After clicking the Download button, The phone must be off
After that, please connect the corresponding device with a USB cable



step 8: After the upgrade is successful, the prompt is as follows



Thanks !