


## Transwan USB 3.0/2.0/1.1 Fiber Extender in Windows 8.1+

Make sure:

- The mini unit (Rx) must be plugged into **USB 3.0** port of local company, and the power supply for this port must be up to **900mA**.
- Window Operation system WIN 8.1 +
- Less 100 Meter (328ft) Multi-mode Fiber cable

Test steps:

- First, connect well for all nodes in the configuration.
- Then power the computer, the Rx LED light will be on (green), Tx unit (Remote side) FIBER light will be on
- Then check the Device Manager interface of the computer, the below new three devices (in the RED circle) will be seen.



In case that “unknown USB device” appears in the interface, please kindly do the following operations

- First, please re-confirm the fiber connection is good
- Then please power off the Tx (remote side) for 20+ seconds, then power it again. Please check of it works or not. If yes, the three devices in the red circle will appear.
- If not, please power off the computer, unplug the power supplier (including Tx’s power supplier and your own device’s power supplier). After 30 seconds, plug all power suppliers again, please re-power the computer.