

Golden Wing industry Service Documents

Golden Wing | Service Bulletin

Subject: vehicle cannot start

Bulletin No.: GW14-05-01

Model Concerned: Rex110/Bull

Date: 2021/11/11

125/Fun 125

Page: 1

Description:

The atv doesn't work I just put it together it won't start.

Solution:

The reason for ATV can't start:

No electricity or no gas.

there is inspection method:

- 1. Whether the wire end of the combination switch falls off
- 2. Hold the brake firmly, the brake light turns on, and press the start switch. Whether the starting motor has a starting sound.
- 3. Check whether there is fire in the high-pressure cap. If there is no fire, check whether the igniter and magneto plugs are disconnected.
- 4. Whether the emergency flame out of the combination switch is pressed.
- 5. Whether the remote flame out is not turned on.