

Fluke 376 FC 1000A AC/DC True-RMS Clamp Meter With Insulated Hand Tool Starter Kit Measures AC/DC Current With Included iFlex

---

**FLUKE** **Fluke 376 FC**  
**1000A AC/DC True-RMS Clamp Meter**



The Fluke 376 FC True-rms Clamp Meter with iFlex is the most advanced troubleshooting tool for industrial and commercial electricians. The 376 is part of the Fluke Connect family of wireless test tools that enable you to log, trend and monitor measurements while remaining safely away from the arc flash zone through Bluetooth connectivity.

Package Includes:

- ◆ Fluke 376 FC True-RMS Clamp Meter
- ◆ 18-inch iFlex® Flexible Current Probe

◆ TPAK magnetic hanging strap

◆ TL75 Test Leads

◆ Soft carrying case

model	F376FC
Measure the alternating current	1000A
Through iFlex alternating current measurement	2500A
Measure the ac voltage	1000.0V
Measure the continuity	≤70Ω
To measure dc current	999.9A
To measure dc voltage	1000.0V
Measuring the resistance	60KΩ
Measuring the surge	500Hz
Measuring the surge	100ms
Regional work in poor lighting conditions	The backlit

Technical indicators	
Conductor diameter can be measured	0.71或18mm max
Working temperature	-14至122°F (-10至50°C)
Storage temperature	-40至140°F (-40至60°C)
Working humidity	<90% @ 10至30°C, <75°C @ 30至40°C
Working at high altitude	0 至2000m
The temperature coefficient of	0.01%/°C (<18°C或>28°C)
Safety standards	EN/IEC 61010-1:2001;1000V CAT III 600V CAT IV

# FLUKE® 376FC



$A \approx$

AC/DC Current

$\Omega$

Resistance test

$\text{—} \text{||} \text{—}$

Capacitance test

$V \approx$

AC/DC Voltage

# Function Interface Introduction

*every engineer deserves it*



# Products display

*every engineer deserves it*





● Front view



● Rear view



● Side view



● Side view



## What's in the box:

- Fluke 376 FC True-RMS Clamp Meter
- 18-inch iFlex® Flexible Current Probe
- TPAK magnetic hanging strap
- TL75 Test Leads
- Soft carrying case

