

YA09 Instruction Mamual



1.0

	Spare Parts List		Quantity
A			1
В			1
С			1
D	=	M12*25	1
Е		8#	1
F			7
G			1
Н			1



1/7

Note: base no included.

