

AGM H3 Detailed steps for software upgrade operation

H3-Driver and upgrade tool download

<https://mega.nz/file/LxNWRbjY#PWvRmYU-YIvMyKY8v0BJSKVOFqUVcl8kbr1fLgYmfJo>

Corresponding system package

1、 H3-EU version download link




https://mega.nz/file/6wtwBbgK#RzPC4aU_IFxwoBi0MjKznmtYLAD5fm8bs6ou6JFlvs4

2、 H3-RU version download link

<https://mega.nz/file/HtVQgZpS#1C9lHK0vd7WCNg2i-vYXyvzUrmN74c0vnVtvBSWygIlg>

3、 H3-US version download link

<https://mega.nz/file/vxUgGRYR#-WykdhLJsbVLNDxNinHuYKHXUEy5KAS45Lphsw3-2UE>

non-recent upgrade operation...				
 Driver_Auto_Installer_EXE_v5.1632.00.zip		2020/12/19 10:32	WinRAR ZIP 压缩...	9,062 KB
 PS1S23WBE62.AGM.RU.HB.R0.HP.S28S88S81H19.S19S29S59HBS79S22.0709.V2.01.TEST3.zip		2021/7/10 18:18	WinRAR ZIP 压缩...	1,555,801...
 SP_Flash_Tool_Selector_exe_Windows_v1.2116.00.000.zip		2021/5/20 16:02	WinRAR ZIP 压缩...	101,885 KB


driver

software


flash tool

Step 1: First, install the driver files ,


If the computer has installed AGM H3 driver, this AGM H3 driver is the same as AGM H3, you can skip to Step 4 directly



Step 2: choose yes as following picture



Step 3: You need to wait for about 15 minutes to delete the driver installation process, please be patient, After the installation is successful, please restart the computer




step 4: Open the upgrade tool

SP_Flash_Tool_Selector_exe_Windows_v1.2116.00.000


名称	修改日期	类型	大小
plugins	2021/4/20 15:55	文件夹	
SP_Flash_Tool_V5	2021/7/10 14:08	文件夹	
SP_Flash_Tool_V6	2021/4/20 15:55	文件夹	
FlashToolSelector.exe	2021/4/22 10:06	应用程序	279 KB
Qt5Core.dll	2021/4/20 15:39	应用程序扩展	6,049 KB
Qt5Gui.dll	2021/4/20 15:39	应用程序扩展	6,963 KB
Qt5Widgets.dll	2021/4/20 15:39	应用程序扩展	5,466 KB
Qt5Xml.dll	2021/4/20 15:39	应用程序扩展	191 KB

codecs	2021/4/20 15:55	文件夹	
imageformats	2021/4/20 15:55	文件夹	
sqldrivers	2021/4/20 15:55	文件夹	
assistant.exe	2021/4/19 16:49	应用程序	1,181 KB
BromAdapterTool.ini	2021/4/19 16:49	配置设置	1 KB
console_mode.xsd	2021/4/19 16:49	XSD 文件	29 KB
CustPT.ini	2021/4/19 16:49	配置设置	1 KB
DA_PL.bin	2021/4/19 16:49	BIN 文件	17,297 KB
DA_PL_CRYPT020.bin	2021/4/19 16:49	BIN 文件	17,297 KB
DA_SWSEC.bin	2021/4/19 16:49	BIN 文件	2,144 KB
DA_SWSEC_CRYPT020.bin	2021/4/19 16:49	BIN 文件	2,144 KB
dl_without_scatter.xml	2021/4/19 16:49	XML 文档	2 KB
download_scene.ini	2021/4/19 16:49	配置设置	1 KB
flash_tool.exe	2021/4/19 16:49	应用程序	10,352 KB
flashtool.qch	2021/4/19 16:49	QCH 文件	8,172 KB
flashtool.qhc	2021/4/19 16:49	QHC 文件	12 KB
FlashToolLib.dll	2021/4/19 16:49	应用程序扩展	1,459 KB
FlashToolLib.v1.dll	2021/4/19 16:49	应用程序扩展	2,909 KB
FlashtoollibEx.dll	2021/4/19 16:49	应用程序扩展	4,925 KB
history.ini	2021/7/10 14:10	配置设置	1 KB
key.ini	2021/4/19 16:49	配置设置	3 KB
msvc90.dll	2021/4/19 16:49	应用程序扩展	556 KB
msvcr90.dll	2021/4/19 16:49	应用程序扩展	641 KB
MTK_AllInOne_DA.bin	2021/4/19 16:49	BIN 文件	17,361 KB
option.ini	2021/7/10 14:10	配置设置	1 KB
phonon4.dll	2021/4/19 16:49	应用程序扩展	261 KB
platform.xml	2021/4/19 16:49	XML 文档	32 KB
QtCLucene4.dll	2021/4/19 16:49	应用程序扩展	873 KB
QtCore4.dll	2021/4/19 16:49	应用程序扩展	2,239 KB
QtGui4.dll	2021/4/19 16:49	应用程序扩展	8,031 KB
QtHelp4.dll	2021/4/19 16:49	应用程序扩展	419 KB


step 5: load software package



step 6: When you finish loading the software, click the download button



step 7: After clicking the Download button, The phone must be off
After that, please connect the corresponding device with a USB cable



step 8: After the upgrade is successful, the prompt is as follows

