
ADAPTOR DATASHEET



QUICK SMA(MALE)-SMA(FEMALE)

QSMA/SMA-JKS



*Dimensions are in mm

Configuration		
Connector 1 Type	Quick SMA Male	
Connector 1 Impedance	50 Ohms	
Connector 1 Polarity	Standard	
Connector 2 Type	SMA Female	
Connector 2 Impedance	50 Ohms	
Connector 2 Polarity	Standard	
Connector Mount Method	None	
Adapter Body Style	Straight	
Electrical Specificatio	ns	
Frequency	DC to 26.5 GHz	
Insertion Loss (dB)	≤ 0.1 xSqt.(f_GHz)	
VSWR /Return Loss	1.20 to 26.5 GHz	
BA . I		
Materials Information	า	
Center Contact	CuBe Gold Plated	
Center Contact	CuBe Gold Plated	
Center Contact Outer Contact	CuBe Gold Plated Stainless Steel	
Center Contact Outer Contact Body	CuBe Gold Plated Stainless Steel Stainless Steel	
Center Contact Outer Contact Body Dielectric	CuBe Gold Plated Stainless Steel Stainless Steel	

While the information has been carefully compiled to the best of our knowledge, nothing is intended as representation or warranty on our part and no statement herein shall be construed as recommendation to infringe existing patents. In the effort to improve our products, we reserve the right to make changes judged to be necessary.

Gwave Technology, Inc.
12630 H Westminster Ave., Santa Ana, CA 92706
www.gwavetech.com