

## How to Upgrade Firmware for iPhone

1. Please connect wireless CarPlay adapter to a USB power adapter



2. Turn on your iPhone's WIFI and join the Wi-Fi named "smartBox\_xxxx" .and enter the password "88888888"

17:30

5G

[Settings](#)

## WLAN

WLAN



✓ smartBox-EE51  
Low Data Mode



### NETWORKS

111111111



126



126-5G



1809-office



1810-5g



222222222



333333333



444444444



999999999



999999999-5G




BB-GL




BB-GL\_5G




3. Visit <http://192.168.1.101> in your Safari.



4. Update the firmware online from your iPhone on that page.



5 You can also submit detailed problem on the update page, so that we can provide better help.



Warm tips:


1. Make sure your iPhone is connecting to the Wi-Fi name “smartBox\_XXXX” in the process of upgrading.
2. It takes 3-4mins to upgrade the firmware. The orange/green light is flashing until the upgrade is successful
3. Do not power off the CarPlay wireless Adapter during the upgrade.
4. If the Carless Adapter is working normally, DO NOT upgrade

### How to Upgrade Firmware for Android



1. Please connect wireless CarPlay adapter to a USB power adapter.
2. Turn on your iPhone’ s WIFI and join the Wi-Fi named “smartBox\_xxxx” , and enter the password “88888888” .




3. Visit <http://192.168.1.101> in your Safari.



4 Click switch P2P and confirm ok.




5 Connect wifi “smartBox\_xxxx” again.



5. Update the firmware online from your iPhone on that page.





6 You can also submit detailed problem on the update page, so that we can provide better help.

5:54

Audio streaming mode Default >

Delayed start Default >

### Problem Description

Car Make

Model Name

Year

Detailed description of the problem:

**Submit**

### Online Update

○ Checking for updates...

**Switch P2P**

5:54

Video streaming mode Default >

Audio streaming mode Default >

Delayed start Default >

### Problem Description

Car Make E.g. Toyota

Model Name E.g. Camry XLE

Year E.g. 2020

Detailed description of the problem:


Please enter text here

**Submit**

Message from 192.168.1.101:  
**switch P2P OK!!!**

**OK**

Copyright © 2020 - 2022



Warm tips:

1. Make sure your iPhone is connecting to the Wi-Fi name “smartBox\_XXXX” in the process of upgrading.
2. It takes 8-10mins to upgrade the firmware. The orange/green light is flashing until the upgrade is successful
3. Do not power off the CarPlay wireless Adapter during the upgrade.
4. If the Carplay wireless Adapter is working normally, DO NOT upgrade